

Survey Summary

Survey Name Survey Start Time Survey Stop Time Company Name

Blue Panther s.r.o. Mezi vodami 29 143 00 Praha Ukázkový protokol 1. 12. 2020 10:04:14 1. 12. 2020 10:04:14

Survey Comments

Ukázkový protokol z akustické Fluke ii910

The estimations provided by this application are designed to be informational only. This model is provided as a rough approximation of the energy savings you could experience by repairing leaks found with the Fluke ii900 Sonic Industrial Imager. The calculator is not a commitment to actual energy savings or an indication of purchase advice. The results presented by this calculator are hypothetical and may not reflect actual results at your facility. The calculations are based on industry averages and proprietary research conducted by the Fluke Corporation. 3.2.4



Survey Summary

Survey Name	Ukázkový protokol	
Survey Start Time	1. 12. 2020 10:04:14	
Survey Stop Time	1. 12. 2020 11:00:22	
Company Name		
Blue Panther s.r.o. Mezi Vodami 29 143 00 Praha		
PDQ Operating Conditions		
Operating Frequency 50Hz Recalculate		
Survey Comments		

2

Ukázkový protokol s prací s akustickou kamerou Fluke ii910



'Ukázkový protokol' Images and Videos Summary

Mode File name

2

Default_0002.as2

Location




'Ukázkový protokol' PDQ Summary

# Mode	File name	Location	Pulse count	Туре
6 🖸	Default_0006.as2		30303	
7 53	Default_0007.as2		28271	



Details

File nameDefault_0002.as2#2TypeImage: Constrained on the state of the



Notes


Transformátor

Photo notes



Details

File name	Default_0006.as2	
#	6	
Туре	🔁 PDQ	
Folder name	Default	
Date and time	1. 12. 2020 10:59:28	
Pulse count per minute	30303	
Discharge Type	External (Corona / Arcing):	100
	Internal:	0%
	Tracking:	0%
	Other:	0%




Weather Note

Notes

Photo notes



Discharge Analysis



This plot is determined for a operating frequency of 50 Hz



Details

File name #	Default_0007.as2 7	
Type Folder name Date and time	PDQ Default 1. 12. 2020 11:00:22	
Pulse count per minute	28271	
Discharge Type	External (Corona / Arcing):	87%
	Internal:	13%
	Tracking:	0%
	Other:	0%




Weather Note

Notes

Photo notes



Discharge Analysis



This plot is determined for a operating frequency of 50 Hz